## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.


Serial No: 10/786,623
Group No. 1626 /Conf. No. 2057
Page 1 of 95
Replacement Sheets





No: 10/786,623 No. 1626 /Conf. No. 2057 2 of 95 Lacement Sheets

FIG. 2B



Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 3 of 95 Replacement Sheets









FIG. 3B













Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 6 of 95 Replacement Sheets

FIG. 6A





Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 7 of 95 Replacement Sheets

FIG. 10 100 78 82 -84 - 86 - 88 <del>-</del> 76

Serial No: 10/786,623 Group No. 1626'/Conf. No. 2057 Page 8 of 95 Replacement Sheets

FIG. 11 100 -72 74 - 78

Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 9 of 95 Replacement Sheets

FIG. 12A






FIG. 12B



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 10 of 95 Replacement Sheets



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 11 of 95 Replacement Sheets





FIG. 15A


FIG. 15B



172 176 170 174

FIG. 15C

FIG. 15D









FIG. 15E



Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 12 of 95 Replacement Sheets




Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 13 of 95 Replacement Sheets




Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 14 of 95 Replacement Sheets

FIG. 16C




Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 15 of 95 Replacement Sheets

FIG. 17



Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 16 of 95



Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057

Page 17 of 95 Replacement Sheets

FIG. 19A1




FIG. 19A2




FIG. 19B




FIG. 19C





FIG. 19D



Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057

Page 18 of 95 Replacement Sheets

FIG. 20A




FIG. 20B




FIG. 20C




FIG. 21A






FIG. 21B




Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 19 of 95 Replacement Sheets

FIG. 22A




Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 20 of 95

FIG. 22B




Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 21 of 95


FIG. 22C




Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 22 of 95 Replacement Sheets




Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 23 of 95 Replacement Sheets



Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 24 of 95 Replacement Sheets



Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 25 of 95



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057

Page 26 of 95 Replacement Sheets

FIG. 26A







FIG. 26B



Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 27 of 95 Replacement Sheets




Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 28 of 95 Replacement Sheets



Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 29 of 95


FIG. 28B - 326 314 -316 328 -- 328 325 323

FIG. 28C



Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 30 of 95

FIG. 29 -340 -338 346 342 348 344 - 350 349



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057

Page 31 of 95

FIG. 31A






FIG. 31B



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 32 of 95



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 33 of 95





FIG. 32B



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 34 of 95

FIG. 33A





FIG. 33B



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057

Page 35 of 95

FIG. 34

404

402


401

400


FIG. 35

-430
-432
-424
-425
-428
-420
-426

Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 36 of 95



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 37 of 95



Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 38 of 95






FIG. 39




Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 39 of 95



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 40 of 95

Replacement Sheets




492

494

Serial No: 10/786,623

Group No. 1626 / Conf. No. 2057

Page 41 of 95 Replacement Sheets



Serial No: 10/786,623

Group No. 1626 / Conf. No. 2057 Page 42 of 95

Replacement Sheets

FIG. 42A





FIG. 42B



Serial No: 10/786,623

Group No. 1626 / Conf. No. 2057

Page 43 of 95






FIG. 43B




FIG. 43C




FIG. 44A





FIG. 44B



Serial No: 10/786,623 Group No: 1626 /Conf. No. 2057

Page 44 of 95

FIG. 45A





FIG. 45B



Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057

Page 45 of 95 Replacement Sheets

FIG. 46A





FIG. 46B



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057

Page 46 of 95 Replacement Sheets

FIG. 46C





FIG. 46D




Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 47 of 95 Replacement Sheets


FIG. 47 566 -

Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057

Page 48 of 95




Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 49 of 95




Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 50 of 95

FIG. 50



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 51 of 95

FIG. 51



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 52 of 95

FIG. 52A





FIG. 52B




Serial No: 10/786,623

Group No. 1626 / Conf. No. 2057


Page 53 of 95

FIG. 53




Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057 Page 54 of 95

FIG. 54A




Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 55 of 95

FIG. 54B



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 56 of 95

FIG. 55



Serial No: 10/786,623

Group No. 1626 / Conf. No. 2057

Page 57 of 95 Replacement Sheets

FIG. 56A

730
732
734
736

FIG. 56B





FIG. 57



Serial No: 10/786,623 Group No. 1626 /Conf. No. 2057

Page 58 of 95 Replacement Sheets

FIG. 58A




FIG. 58C




FIG. 58B





FIG. 59



Serial No: 10/786,623

Group No. 1626 / Conf. No. 2057 Page 59 of 95

Page 59 of 95 Replacement Sheets

FIG. 60A




FIG. 60B





FIG. 60C



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057

Page 60 of 95 Replacement Sheets

FIG. 61




FIG. 62




FIG. 63A





FIG. 63B



Serial No: 10/786,623

Group No. '1626'/Conf. No. 2057 Page 61 of 95

FIG. 64A





FIG. 64B



Serial No: 10/786,623

Group No. 1626'/Conf. No. 2057

Page 62 of 95 Replacement Sheets

FIG. 65

860
866
878
878
878
878
878

FIG. 67A






FIG. 67B




Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 63 of 95

FIG. 67C




Serial No: 10/786,623 Group No. 1626'/Conf. No. 2057 Page 64 of 95

FIG. 68A



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 65 of 95 Replacement Sheets


FIG. 68B



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 66 of 95


FIG. 69A FIG. 69B -910 910-906 906

FIG. 69C



Serial No: 10/786,623 Group No.·1626 / Conf. No. 2057 Page 67 of 95 Replacement Sheets


FIG. 69D




Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057

Page 68 of 95 Replacement Sheets

FIG. 70





Serial No: 10/786, Serial No: 10/786, 623 Group No. 1626 / Conf. No. 2057

Page 69 of 95

FIG. 71B





FIG. 71C



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 70 of 95







FIG. 73



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 71 of 95 Replacement Sheets



Serial No: 10/786,623 Group No.·1626 / Conf. No. 2057 Page 72 of 95 Replacement Sheets



Serial No: 10/786,623 Group No. ·1626 '/Conf. No. 2057 Page 73 of 95

FIG. 75B







FIG. 75C



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 74 of 95






Serial No: 10/786,623 Group No. 1626 '/Conf. No. 2057 Page 75 of 95


FIG. 76A

FIRST STEP: C. SCREEN





—FIG. 76B—

SECOND STEP: RADIO RCV DIRECTION FINDER



Serial No: 10/786,623 Group No. 1626 '/Conf. No. 2057 Page 76 of 95





Serial No: 10/786,623 Group No. ·1626 ·/Conf. No. 2057 Page 77 of 95





FIG. 78



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 78 of 95

FIG. 79A





FIG. 79B



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 79 of 95 Replacement Sheets

FIG. 80




FIG. 81A





FIG. 81B



Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057 Page 80 of 95

FIG. 81C





FIG. 81D



Serial No: 10/786,623 Group No. ·1626 '/Conf. No. 2057 Page 81 of 95

FIG. 82 -1778 

Serial No: 10/786,623

Group No. 1626 / Conf. No. 2057

Page 82 of 95

FIG. 83





FIG. 84




Serial No: 10/786,623 Group No. 1626 / Conf. No. 2057

Page 83 of 95

FIG. 85A 1914 - 1910 1912 1916 FIG. 85B . - 1918 1922 1920-1923 -

FIG. 85C



erial No: 10/(85,523 coup No. 1626 /Conf. No. 2057 ige 84 of 95 eplacement Sheets




FIG. 1A

roup No. 1626 /Conf. No. 2057 age 85 of 95 eplacement Sheets





FIG. 1B

erial No: 10/786,623 roup No. 1626 /Conf. No. 2057 age 86 of 95 eplacement Sheets





erial No: 10/786,623 roup No. 1626 /Conf. No. 2057 age 87 of 95 eplacement Sheets



erial No: 10/786,623 roup No. 1626 /Conf. No. 2057

age 88 of 95 splacement Sheets




FIG. 5A

erial No: 10/786,623 roup No. 1626 /Conf. No. 2057 age 89 of 95 eplacement Sheets



erial No: 10/786,623 roup No. 1626 /Conf. No. 2057 age 90 of 95 eplacement Sheets




erial No: 10/786,623 roup No. 1626 /Conf. No. 2057


age 91 of 95




erial No: 10/786,623 coup No. 1626 /Conf. No. 2057 age 92 of 95 eplacement Sheets



erial No: 10/786,623 coup No. 1626 /Conf: No. 2057 age 93 of 95 eplacement Sheets



erial No: 10/786,623 roup No. 1626 /Conf. No. 2057 age 94 of 95 eplacement Sheets



erial No: 10/786,623 roup No. 1026 /Conf. No. 2057 age 95 of 95 eplacement Sheets

